

APPENDIX 3

QUOTE

DATE: 3/11/2024

TO:
Cllr Stephanie Gill
Clavering PC

COMMENTS

QUOTES FOR WORKS ON 3 BENCHES AND PICKET PALE FENCE REPAIR AT WATER PUMP

Quote 1

Repair picket pale fencing around water pump on Hill Green
Replacement of 5(five) missing/loose pales with suitable pressure treated softwood. Clear existing posts of overgrown ivy.
Parts/labour to replace and clear of vegetation £80

Quote 2

Repair/clean of wooden bench dedicated to Richard Whitting:
This is an oak framed bench and is in very good condition. It is lightly covered in lichen/moss and requires a general clean. No treatment necessary
Recommend this seat is cleared of lichen/moss before winter £35

Quote 3

Repair bench marked 'Eggies Bench'
On close examination this bench has several loose joints and areas of completely rotten wood supporting the seating slats. This bench requires extensive repair particularly around the joints and side supports. It is in my opinion beyond economic repair for a public bench and should be removed from site before a member of the public is injured.

Quote 4

Bench outside the Christian Centre marked Clavering PC
This bench requires some minor securing work to some loose slats. There has been a fairly recent repair to the rear slats which although not ascetically pleasing to the eye is certainly sufficient and is adequately secured and supported. Otherwise, this seat is in good structural repair. At some point painted with a dark brown preservative, this is now wearing away and requires treatment in Spring/Summer 2025.

Cost to repair £20. Cost of bench preparation and treatment in summer 2025 £60